

1607 S. Dakota Ave. • Sioux Falls, SD 57105 Doug (605) 201-6116 • Don (605) 366-2163

Member InterNACHI - International Association of Certified Home Inspectors

Client:	Property Location:	- N- of 12 (12)			
Address:		Sioux Falls, SD			
City:		57105			
State, Zip:					
Date of inspection: Jun 24, 2016 Time: 8:00 am	Weather conditions: Sunny	Outside temperature:	66	٥F	

Hennies Home Inspection performed a home inspection at the above address for the sole use of the above client.

This report is confidential and the use by any unauthorized persons is prohibited.



This is our report of the readily accessible areas of the above listed site, in accordance with the terms and conditions accepted in the INSPECTION AGREEMENT, which is part of this report and incorporated therein. This agreement is not transferable or assignable. The Company accepts no responsibility for use or misinterpretation by third parties and third parties who rely on it in any way do so at their own risk. Please read the remarks on each page and call us for an explanation of any aspect of the report that you do not fully understand.

WHEREAS, the customer, hereinafter called the CLIENT, has requested that the inspector perform an inspection of the above listed property, and the inspector, hereinafter called the COMPANY has agreed to conduct the inspection.

NOW THEREFORE, in consideration of the mutual covenants of the parties and other good and valuable consideration, it is agreed as follows:

The COMPANY agrees to conduct an inspection for the purpose of informing the CLIENT of major non concealed deficiencies in the condition of the property. The inspection shall be done in accordance with the South Dakota and the NACHI standards of practice. It is agreed that this report pertains only to readily accessible areas of the building and is limited to visual observation of apparent conditions only at the time of the inspection. No moving of furniture, stored items or appliances, disassembly of equipment or opening of walls was performed. All components and conditions which by the nature of their location are concealed, camouflaged or unsafe to inspect are excluded from this report. The inspection and report are conducted for the sole, confidential and exclusive use and possession of the CLIENT. The report shall include only the following:

- Structural condition, basic electrical and plumbing systems, heating and air conditioning systems (visual inspections only), kitchen appliances, foundations and basements. The appliance inspection is a basic test with no internal testing conducted.
- General interior including walls, ceilings, floors, a representative number of windows, insulation and ventilation.
- General exterior including drainage, roof, gutter, chimney, siding.

CLIENT understands and acknowledges that COMPANY's inspection is limited to those items expressly described above. It is agreed that the components and conditions beyond the scope of the inspection include, but are not limited to:

- Environmental problems, including but not limited to, gas including radon (optional), the presence of mold, lead paint, formaldehyde, asbestos, water and air born hazards
- Wells underground storage tanks, water conditioners, humidifiers, sewer, septic systems, alarm systems, lawn sprinklers, swimming pools, fire and safety equipment, central vacuums, heat exchangers, yard lights hot tubs, playground equipment, intercoms, and heat sensors.
- Insects such as termites and carpenters ants (optional), hidden or latent defects.

CLIENT agrees that in the event of a claim against COMPANY, any such action must be initiated within one year from the date of the original inspection. The CLIENT further agrees to allow COMPANY to inspect a claim prior to any repairs or waive the right to make the claim. The CLIENT agrees not to disturb anything which may constitute as evidence relating to the complaint, except in the case of an emergency.

It is further understood and agreed that should COMPANY, and its agents or employees be found liable for any loss or damages resulting from a failure to perform any of its obligations, including but not limited to negligence, breach of contract, or otherwise, then the liability of COMPANY and/or its agents and employees shall be limited to a sum equal to the amount of the fee paid by the CLIENT for the inspection and report.

This agreement constitutes the entire understanding of the parties with regard to this matter and no statements, oral or otherwise, shall be enforceable unless made in writing and signed by both parties. Any comments made by the inspector are simply a courtesy to the buyer. Should any element of this agreement be declared void it shall be stricken and the remaining provisions shall remain in full force and effect.

It is further understood that COMPANY, its officers and or employees, assume no liability and shall not be responsible for the cost of repairing or replacing any unreported defect or deficiency, either current or arising in the future. This limitation of liability shall include and apply to all consequential damages, bodily injury or for any property damage of any nature.

The inspection and report are not intended or to be used as a guarantee or warranty, expressed or implied, regarding the adequacy, performance or condition of an inspected structure, item or system. Nor is the inspection a determination of compliance with applicable codes, laws or regulation.

The CLIENT acknowledges that he/she has read this agreement in full, prior to signing the same, and understands and agrees to all terms and conditions.

Company Representative	Jun 24, 2016	Client		Jun 24, 2016
The same shall be due and payable upo	n completion of the inspect	ion		
The CLIENT agrees to pay the inspector	or the sum of \$	for performing its service with invoice #	5705	



SUMMARY

List of electrical, mechanical and plumbing items not operating, roof leaks or other major deficiencies:

There are moisture stains, rust and an opening at the furnace/water heater chimneys. The furnace/water heater chimney may not have proper clearance where they pass thru the floor joist, (all visible from the lower level) Due to the age of the furnace and the condition of the chimneys we recommend having the furnace, chimneys and heat exchanger cleaned, serviced, and evaluated by a professional HVAC contractor before closing.

The following items are important but not major deficiencies at this time:

There is no city electrical inspection sticker on electrical panel door. The A/C circuit breaker is too large. The manufacturer calls for no larger than a 20 amp circuit breaker and a 30 amp breaker is in place.

Building Permits / Remarks:

2008-09-18 128591 DECK ADDITION ERIK HOVLAND 700.00

2009-07-10 133079 INSTALL STONE ON HOUSE/GARAGE ERIC HOVLAND 1100.00

2007-09-07 122183 REMODEL KITCHEN ERIK HOVLAND 1000.00

2008-05-16 125888 2 REPLACE ENTRY DOOR ERICK HOVLAND 3000.00

2009-09-11 134495 INSTALL EGRESS WINDOWS TWO ERIK HOVLAND 500.00

1997-08-13 56566 RESHINGLE HOUSE NEUMAN'S ROOFING 2500.00

1990-08-06 21424 INSTALL BAY WINDOW OVRELID CONSTRUCTION 3000.00

1989-04-20 16251 ADDITION TO HOUSE FAMILY ROOM/ADD BATH OVRELID CONST 27000.00 2009-11-20 135936

REMODEL FAMILY ROOM SHEETROCK CEILING ERIK HOVLAND 500.00

2014-08-13 174041 RESHINGLE HOUSE & GARAGE WEBER CONSTRUCTION I 9000.00



Image information: Opening in the furnace/water heater chimney.



Image information: Rusting and moisture stains on the furnace chimney.

This report consists of 13 pages. The following pages cover in greater detail the items which are a part of this inspection. Additional recommendations may also be found on the following pages.



STRUCTURAL

TYPE OF	● Single	
BUILDING	☐ Gable Roof ☐ Shed ☒ Hip ☐ Flat ☐	
STRUCTURE	Foundation: Poured concrete Block Brick Block & Brick Block & Brick Foundation:	
	Posts/Columns: Steel Masonry Wood Concrete Not Visible [N/A
	Floor Structure: Wood plank on 2x8's	
	Wall Structure: 2x4	
	Roof Structure: Wood plank on rafters	
	Water damage: Some signs Extensive None observed	
	Signs of abnormal condensation: Some signs Extensive None observed	
	Major structural defects: Yes X No	
Remarks: There is	cracking of the house and garage foundations.	
	BASEMENT (OR LOWER LEVEL)	
BASEMENT	☐ Full ● Partial ☐ None ☐ Slab on grade	
	Walls: ⊠Open ⊠Closed Ceiling: ⊠Open ⊠Closed	
SUMP PUMP	● Tested ○ Not tested □ Water observed in sump pit Dry	Satisfactory
	Extension at Exterior XYes No	□N/A
	☐ Sealed pit ☐ Radon mitigation system	See remarks
FLOOR	⊠ Concrete □ Dirt □	Satisfactory
	Resilient Tile Vinyl	□ N/A
	☐ Tile ☐ Laminate ☐ Engineered Wood ☐ VAT	See remarks
FLOOR DRAIN	● Tested ○ Not Tested	Satisfactory
		□ N/A
		See remarks
BASEMENT	⊠ Some signs	
DAMPNESS	☐ None observed	
CRAWL SPACE		Satisfactory
		□ N/A
	Floor: Concrete: Dirt: Wood to earth contact	See remarks
	Dampness: Some signs: Extensive None observed	
	rior sump pump discharge line should be directed to take the water away from the foundation	n. There are
moisture stains or	the lower level interior wall and on the foundation wall under the laundry room window.	

HEATING

HEATING	Brand Name: Trane	Age: 1991	Efficiency: <80 %	☐ Satisfactory
SYSTEM	No. 1 Capacity: 80,000 btu's/hr			□ N/A
	Model # tud080c93640	Serial # f49591	877	⊠ See remarks
	Brand Name:	Age:	Efficiency: %	
	No. 2 Capacity			
	Model #	Serial #		.
	Fuel: ⊠ Gas □ Oil □ Electric □			
	Type: Forced air furnace			
	When turned on by thermostat Fired	Olid not fire		
FUEL SUPPLY	□ Public gas supply □ Tank □ Electricity			
	Fuel supply shutoff location: Next to the Furna	ce		
HEAT EXCHANGER	⊠ Heat Exchanger Not Inspected			
FILTER	☑ Disposable ☐ Washable ☐ Electronic ☐	Ultraviolet F	ilter: O Clean O Dirty	□ N/A
HEAT	Heat source in each room: ●Yes ○No			
DISTRIBUTION	⊠ Ductwork	Baseboard conv	vectors Radiant	See remarks
HUMIDIFIER	⋈ Not functioning	○ Clean		□ N/A
SUPPLEMENTARY HEAT	Location: Type:			
	Master bedroom Electric	wall heater	See remarks	Satisfactory
			See remarks	☐ Satisfactory
	the age of the furnace and the condition of the cheaned, serviced, and evaluated by a professional	HVAC contracto		
COOLING	COOLIN		F.C	[V] Catinforter
COOLING		Age: <u>1999</u>	Efficiency: ???? SEER	× Satisfactory
	No. 1 Condensing Unit Capacity: 2 tons			□ > T/A
	M. 1.1 // al-24 fb	C - 1-1 // 0005441	1205	□ N/A
	Model # ck24-1b	Serial # 9905441		□ N/A □ See remarks
	Circuit Breaker: 30 amps	Max Allowed:	20 amps	See remarks
	Circuit Breaker: 30 amps Brand Name:	Max Allowed:		See remarks
	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity:	Max Allowed: Age:	20 amps	See remarks
	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model #	Max Allowed: Age: Serial #	20 amps Efficiency: SEE	See remarks
	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model # Circuit Breaker:	Max Allowed: Age: Serial # Max Allowed:	20 amps Efficiency: SEE	See remarks
	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model # Circuit Breaker: Tested Not tested Window units not	Max Allowed: Age: Serial # Max Allowed: tested	20 amps Efficiency: SEE	See remarks
Remarks:	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model # Circuit Breaker:	Max Allowed: Age: Serial # Max Allowed: tested	20 amps Efficiency: SEE	See remarks
Remarks:	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model # Circuit Breaker: Tested Not tested Window units not	Max Allowed: Age: Serial # Max Allowed: tested	20 amps Efficiency: SEE	See remarks
Remarks:	Circuit Breaker: 30 amps Brand Name: No. 2 Condensing Unit Capacity: Model # Circuit Breaker: Tested Not tested Window units not	Max Allowed: Age: Serial # Max Allowed: tested	20 amps Efficiency: SEE	See remarks



PLUMBING AND BATHROOM

WATER	Brand Name: Rheem	Age: 2016		
HEATER	Model # pr0g40-38n rh62	Serial # q051623936	N/A	
	Brand Name:	Age:	See remarks	
	Model #	Serial #		
	Gas Electric Integral with heating sys	tem Fuel cutoff location: Next to the	ne Water Heater	
	Capacity 40 Gal. Ample for 4-5 people		ension	
WATER SERVICE	WaterSupply: Public Private Not kno	own Pipe: Copper		
ENTRANCE PIPE	Main shutoff location: at the meter		See remarks	
PIPES	☐ Plastic ☐ Galvanized ☐ Brass ☒ Copp	er Unknown Cross connections:	No Satisfactory	
	Water flow: Tested Not Tested Leaks	: O Some signs None observed	See remarks	
DRAIN/WASTE	Drain/Waste/Vent Pipes: ⊠ Copper ☐ Galvan	ized Brass Plastic Lead		
VENT	Leaks: Osome signs None observed	Waste Disposal: • Public Priv	vate Not known	
Water Softener/ Purification	Water softener (not tested)	rification system (not tested) N	'A	
Remarks:				
BATHROOM NO 1	Location: Lower level	BATHROOM NO 2 Location: Main	floor	
Built in tub Leg tub Stall shower Whirlpool		⊠ Built in tub		
Sink Fan Vanity Window Nampeer Na		⊠ Toilet		
Shower wall: Fibe		Shower wall: Ceramic tile		
Floor covering: Tile		Floor covering: Tile		
Leaks: None observed ☐ Slow drain ☒ Satisfactory		Leaks: None observed	Slow drain Satisfactory	
BATHROOM NO 3	Location: Master bathroom	BATHROOM NO 4 Location:		
☐ Built in tub ☐ Leg tub ☐ Stall shower ☐ Whirlpool		Built in tub Leg tub Stall shower Whirlpool		
⊠ Toilet ⊠ Sink	⋉ Fan	☐ Toilet ☐ Sink ☐ Fan ☐ Vanity ☐ Window		
Shower wall: Fibe	erglass	Shower wall:		
Floor covering: Til	le	Floor covering:		
Leaks: None obse	erved Slow drain Satisfactory	Leaks:	Slow drain Satisfactory	
BATHROOM NO 5	Location:	BATHROOM NO 6 Location:		
Built in tub	Leg tub Stall shower Whirlpool	Built in tub Leg tub Stall shower Whirlpool		
☐ Toilet ☐ Sink	Fan Vanity Window	☐ Toilet ☐ Sink ☐ Fan ☐ Vanity ☐ Window		
Shower wall:		Shower wall:		
Floor covering:		Floor covering:		
Leaks:	Slow drain Satisfactory	Leaks:	Slow drain Satisfactory	
Remarks: The mas	ter bathroom sink stoppers do not work.			

ELECTRICAL

SERVICE	Capacity: 100 Amps 220 Volts	Satisfactory
ENTRANCE CABLE	Service line entrance: Overhead Underground	See remarks
	Conductor material: Copper • Aluminum	
MAIN PANEL	Location: Lower level east wall	Satisfactory
	Main disconnect: 100 Amps	□ N/A
	⊠ Grounded □ Panel Index	⊠ See remarks
	☐ Fuses ☑ Circuit Breakers	
SUB PANEL	Location:	Satisfactory
	Main disconnect: Amps	⊠ N/A
		See remarks
CIRCUITS AND	Quantity: Ample Full Branch wiring: Copper Aluminum	Satisfactory
CONDUCTORS	Wiring method: ⊠ Romex ⊠ BX ☐ Knob and tube ☐ Double tap breaker	See remarks
OUTLETS		Satisfactory
	GFCI: Exterior Garage Kitchen Bathroom(s) Three	See remarks
DETECTORS	□ Carbon monoxide alarms not tested	Satisfactory
	Smoke Detectors: Satisfactory • Additional Recommended	⊠ See remarks
•	ly with the U.S product and safety commission guidelines. The A/C circuit breaker is too larges for no larger than a 20 amp circuit breaker and a 30 amp breaker is in place. The outlet for	
Image information	Image information:	



KITCHEN AND APPLIANCES

CABINETS /		★ Satisfactory
COUNTERTOP		See remarks
SINK	Plumbing leaks: O Some signs: None observed Slow drain	★ Satisfactory
	Disposal: • Operating Not operating NA	See remarks
DISHWASHER	Brand: Maytag • Operating Not operating N/A	★ Satisfactory
	Brand: Operating Not operating	See remarks
	The dishwasher was tested on one cycle only. The test does not comply that the dishwasher wil your requirements.	l clean the dishes to
RANGE/OVEN	Brand: Maytag	
TO IT (GE) O VEIV	Brand: Wall oven Operating Gas Electric	N/A
		See remarks
	Brand: Cooktop Operating Gas Electric *temperatures of the heat settings were not tested.*	See Temarks
REFRIDGERATOR		
	#2 Brand: Operating Icemaker Age Yrs	∏ N/A
	Joperating Treemaker Tige 115	See remarks
MICROWAVE	#1 Brand: Maytag \overline Operating Age 2007 Yrs \square N/A	
	#2 Brand: Operating Age Yrs Too Low	See remarks
VENTILATION	Exhaust fan Ductless Vented to outside N/A	
	Filter Light	See remarks
FLOOR	Type: Dura-ceramic	
COVERING		See remarks
CLOTHES	Brand: LG \(\sum \)Operating \(\sum \)Not tested \(\sum \)N/A	
WASHER		See remarks
CLOTHES	Brand: LG	Satisfactory
DRYER	Vented to: Out west wall	See remarks
Remarks:		

INTERIOR

FLOORS	⊠Hardwood ☐Softwood ☐Tile ⊠Wall-to-Wall Carpet ☐Vinyl	Satisfactory
	Resilient Laminate Engineered Wood	See remarks
WALLS	⊠Plaster ⊠Drywall □Wood □Masonry □	Satisfactory
		See remarks
CEILINGS	⊠Plaster ⊠Drywall □Wood □	Satisfactory
	☐ Moisture stains ☐ Closet Globe	See remarks
STAIRS /	☐ Balcony ⊠ Stairs ⊠ Railings ☐ Balusters ☐ N/A	Satisfactory
RAILINGS		See remarks
FIREPLACE	Main floor Gas Fan: Not operating Damper: N/A	Satisfactory
	Fan: Damper:	N/A
	Fan: Damper:	⊠ See remarks
	☐ Flue liner ☐ Partially observed ☐ Clean chimney before use ☐ Gas fireplace damper	
DOORS		Satisfactory
(INSIDE)		See remarks
WINDOWS	∑ Double hung	Satisfactory
AND SKYLIGHTS		□ N/A
		See remarks
	☐ Roof windows and skylights ☐ Moisture stains ☐ Extensive	
	ATTIC	
ACCESS	How inspected Looked in Not inspected N/A	Satisfactory
	☐ Stairs ☐ Pulldown ☑ Scuttlehole ☐ No access	See remarks
MOISTURE	Some signs ○ Extensive ● None observed □ Condensation	
STAINS	Roof leaks: Some signs Extensive None observed	
STORAGE	☐ Floored ⊠ Not floored	
INSULATION	Type: Blown in Cellulose Average inches: 12 +/-	Satisfactory
	Installed in: Rafters Floor Approx. R Rating: 38 +/-	See remarks
VENTILATION	☐ Window(s) ☐ Attic fan ☐ Whole house fan ☐ Turbine	Satisfactory
	☐Ridge vent ☐ Soffit vent ☐ Roof vent(s) ☐ Gable end louvers	□ N/A
	Attic fan	See remarks
	six inches of insulation above the garage. The attic access in the master bedroom closet is notice. The attic was inspected from the attic access only due to insulation, lack of walking boards.	

ROOFING SYSTEM

ROOF	Location:	Materials	Age		
COVERING	Throughout	Laminated shingles	2014	See remarks	★ Satisfactory
				See remarks	Satisfactory
				See remarks	☐ Satisfactory
	How inspected Walked on				
	Defective Shingles				
FLASHING		Copper			
		Lead			See remarks
CHIMNEY	☐ Brick ☐ Metal ☐ Block	PVC		□ N/A	Satisfactory
	⊠In chase				See remarks
GUTTERS AND		Copper Vinyl	Wood	□ N/A	Satisfactory
DOWNSPOUTS	Extensions: XYes No				See remarks
Remarks: There is	some debris in the gutters.				
		EXTERIOR			
EXTERIOR	Doorbell: Operating No	t operating N/A			Satisfactory
DOORS					See remarks
WINDOWS	Window trim: Signs of de	terioration	None observed		★ Satisfactory
AND SKYLIGHTS					See remarks
FAUCETS	Faucets:	Frost free Not frost free	ee Not tested		Satisfactory Satisfactory
					See remarks
EXTERIOR	Location:	Materials			
WALL COVERING	Front	Man made stone & Wood	d siding	See remarks	☐ Satisfactory
COVERNO	Balance	Wood siding		See remarks	Satisfactory
	Bushes				
EXTERIOR	Signs of deterioration	Extensive None observ	/ed		Satisfactory
TRIM					See remarks
GARAGE/	⊠ Garage	etached		□ N/A	Satisfactory
CARPORT	Garage shelving Stored	Items			⊠ See remarks
GARAGE DOOR	⊠Door operator	☐ Safety reverse ⊠S	Safety reverse eyes	□ N/A	Satisfactory
	Safety reverse too high	Safety reverse adjustment			See remarks
	se to garage door is an interior o				
	ront of the house & garage and g ere is one loose stone at the bott		_		
the garage floor.	ere is one loose stone at the bott	om row or the south garag	ge stone panen The	e is crucking un	a settlement of

GROUNDS

GRADING	General grading, slope, and drainage:	See Remarks	☐ Satisfactory
	Grading and slope at house wall (within 5 feet from building)	⊠See Remarks	Satisfactory
SIDEWALK	⊠ Concrete		
AND WALKWAY	□		See remarks
DRIVEWAY			Satisfactory
			See remarks
WINDOW	Metal	□ N/A	☐ Satisfactory
WELLS			See remarks
RETAINING WALL	☐ Brick ⊠ Block ⊠ Stone ⊠ Wood ☐ Concrete	N/A	☐ Satisfactory
WALL			⊠ See remarks
TREES AND	Dead and hanging branches	□ N/A	☐ Satisfactory
SHRUBBERY			⊠ See remarks
FENCING	☐ Metal ☐ Wood ☐ Vinyl ☐	⊠ N/A	☐ Satisfactory
			See remarks
wells.			
DECK/	Signs of deterioration Extensive None observed		
BALCONY	On grade Raised Wood Metal Composite Handrail		N/A
	Conferme Composite Composite Comment		See remarks
PATIO	Concrete Pavers Brick Flagstone	∏ N/A	Satisfactory
			⊠ See remarks
FRONT PORCH	Floor: Wood Concrete Railing/Guardrail	∏ N/A	
			See remarks
OUTBUILDINGS	Flooring: Concrete	[Not Inspected
	some cracking of the patio. Cracks and joints should be sealed to prevent wa	ater penetration.	

Continued from page	REMA Subject	ARKS
Continued from page	Subject	
Continued from page	Subject	
Image information: Pobris is		Image information. Tree branches need to be trimmed away

from the shingles.